



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

## Condition Report

### Sale 1825 - 10/12/2018 10:00:00 - Live Webcast General Medical Equipment and Endoscopy Auction - PART 1

**Sale Date** 10-12-2018 10:00

**Location:** Malmesbury. Wiltshire, Uk

**Viewing:** Friday 7th Decemeber 12PM - 5PM and morning of the sale from 08:30AM

**Removal:** By 4PM on Monday 17th December 2018 - Late collection charges will be incurred after this date

**These reports are compiled by our Medical Engineering Team and are for guidance only - all lots are sold as seen, as per our Conditions of Sale. We recommend that wherever possible you inspect lots prior to purchase.**

#### Lot 1 Olympus CYF-4A Fiber Cystoscope | SN 1000212

- Condition Report:
- **Insertion Tube** – With kink at the end of the control handle
  - **Bending mechanism & Angulation Control** – Good movements and lock
  - **Light Guide Cable & Light Transmission** – Good
  - **Objective Lens & Focussing** – Poor optics, large patches of damaged fibres
  - **Remote Control Switches** – N/A
  - **Distal End** – Satisfactory condition
  - **Image Quality** – Poor image
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Leaking
  - **Overall Condition** – Poor optice and leaking . Scuffs on the control handle.
  - **Dimension:** 6 x 350 mm

#### Lot 2 Olympus CF-P20S Fiber Sigmoidoscope | SN 2615735 | AN 358254

- Condition Report:
- **Insertion Tube** – Satisfactory condition
  - **Bending mechanism & Angulation Control** – Good movements and locks
  - **Light Guide Cable & Light Transmission** – Good
  - **Objective Lens & Focussing** – Good
  - **Remote Control Switches** – N/A
  - **Distal End** – Good condition (distal cap missing)
  - **Image Quality** – Good image (with signs of a few broken fibres)
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Pass
  - **Overall Condition** – Satisfactory overall physical condition with signs of wear on the handle
  - **Dimension:** 12 x 600 mm

#### Lot 3 Olympus GIF-2T240 Video Gastroscope | SN 2531261



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

- Condition Report:
- **Insertion Tube** – Good condition
  - **Bending mechanism & Angulation Control** – Good movements and locks
  - **Light Guide Cable & Light Transmission** – Good
  - **Objective Lens & Focussing** – Good
  - **Remote Control Switches** – Fully functional
  - **Distal End** – Good condition
  - **Image Quality** – Good image
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Pass
  - **Forceps Elevation Mechanism** – Functional
  - **Overall Condition** – Good overall condition
  - **Dimension:** 12 x 1000 mm
- 

#### Lot 4 Olympus CF-P20S Fiber Sigmoidoscope | SN 2536601

- Condition Report:
- **Insertion Tube** – Satisfactory condition
  - **Bending mechanism & Angulation Control** – Good movements and locks
  - **Light Guide Cable & Light Transmission** – Good
  - **Objective Lens & Focussing** – Good
  - **Remote Control Switches** – N/A
  - **Distal End** – Good condition
  - **Image Quality** – Good image (with signs of a few broken fibres)
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Pass
  - **Overall Condition** – Satisfactory overall condition with signs of wear on the handle
  - **Dimension:** 12 x 600 mm
- 

#### Lot 5 Olympus CF-100S Video Sigmoidoscope | SN 2220762

- Condition Report:
- **Insertion Tube** – Satisfactory condition
  - **Bending mechanism & Angulation Control** – Good movements (R/L lock is slightly loose)
  - **Light Guide Cable & Light Transmission** – Good
  - **Objective Lens & Focussing** – Not tested
  - **Remote Control Switches** – Not tested
  - **Distal End** – Satisfactory condition
  - **Image Quality** – Not tested
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Fail
  - **Overall Condition** – Satisfactory physical condition but leaking. Processor not available to check image quality. Auxiliary water connector is damaged.
  - **Dimension:** 13 x 600 mm
- 

#### Lot 6 Olympus BF 1T200 Bronchoscope | SN 2410333 | AN S8162



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

- Condition Report:
- **Insertion Tube** – Satisfactory condition
  - **Bending mechanism & Angulation Control** – Good movements
  - **Light Guide Cable & Light Transmission** – Good
  - **Objective Lens & Focussing** – Satisfactory
  - **Remote Control Switches** – Fully functional
  - **Distal End** – Good condition
  - **Image Quality** – Satisfactory image (slightly blur)
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Pass
  - **Overall Condition** – Satisfactory overall condition
  - **Dimension:** 6 x 450 mm

---

#### Lot 7 Leiseqang LM-Flex 7 Hysteroscope

- Condition Report:
- **Insertion Tube** – Satisfactory condition
  - **Bending mechanism & Angulation Control** – Good movements (control cover is missing)
  - **Light Guide Cable & Light Transmission** – Good light transmission (no fibre optic cable)
  - **Objective Lens & Focussing** – Satisfactory
  - **Remote Control Switches** – N/A
  - **Distal End** – Good condition
  - **Image Quality** – Satisfactory image (slightly blur)
  - **Instrument Channel (s)** –
  - **Leak Test** – Not tested
  - **Overall Condition** – Satisfactory overall condition
  - **Dimension:** 3 x 200 mm

---

#### Lot 8 Vision Science CST-5000 Video Cystoscope | SN CS20209P | AN 155583

- Condition Report:
- **Insertion Tube** – Good condition
  - **Bending mechanism & Angulation Control** – Good movements
  - **Light Guide Cable & Light Transmission** – Not tested
  - **Objective Lens & Focussing** – Not tested
  - **Remote Control Switches** – Not tested
  - **Distal End** – Good condition
  - **Image Quality** – Not tested
  - **Instrument Channel (s)** –
  - **Leak Test** – Leak detected
  - **Overall Condition** – Good physical condition. Processor not available to check image quality.
  - **Dimension:** 3 x 200 mm



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

Leak tester included

---

**Lot 9 Vision Science CST-5000 Video Cystoscope | SN 850174 Endoscope**

- Condition Report:
- **Insertion Tube** – Good condition
  - **Bending mechanism & Angulation Control** – Good movements
  - **Light Guide Cable & Light Transmission** – Not tested
  - **Objective Lens & Focussing** – Not tested
  - **Remote Control Switches** – Not tested
  - **Distal End** – Good condition
  - **Image Quality** – Not tested
  - **Instrument Channel (s)** –
  - **Leak Test** – Leak detected
  - **Overall Condition** – Good physical condition. Processor not available to check image quality.
  - **Dimension:** 3 x 200 mm

Leak tester included

---

**Lot 10 Vision Sciences CST-5000 Video Cystoscope (No Case) | SN 850170**

- Condition Report:
- **Insertion Tube** – Good condition
  - **Bending mechanism & Angulation Control** – Good movements
  - **Light Guide Cable & Light Transmission** – Not tested
  - **Objective Lens & Focussing** – Not tested
  - **Remote Control Switches** – Not tested
  - **Distal End** – Good condition
  - **Image Quality** – Not tested
  - **Instrument Channel (s)** –
  - **Leak Test** – Leaking
  - **Overall Condition** – Good physical condition. Processor not available to check image quality.
  - **Dimension:** 3 x 200 mm

---

**Lot 11 Pentax FI-13RBS Fiber Intubation Scope | SN G110156**

- Condition Report:
- **Insertion Tube** – Good condition
  - **Bending mechanism & Angulation Control** – Good movements
  - **Light Guide Cable & Light Transmission** – Good light transmission (no fibre optic cable)



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

- **Objective Lens & Focussing** – Good
- **Remote Control Switches** – N/A
- **Distal End** – Good condition
- **Image Quality** – Clear image
- **Instrument Channel (s)** – Clear
- **Leak Test** – Leaking
- **Overall Condition** – Good physical condition with clear image but leaking
- **Dimension:** 4 x 500 mm

---

#### Lot 12 Pentax FI-13RBS Fiber Intubation Scope | SN G110078

- Condition Report:
- **Insertion Tube** – Satisfactory condition (with a dent close to handle)
  - **Bending mechanism & Angulation Control** – Good movements
  - **Light Guide Cable & Light Transmission** – One of the light channels is not working (no fibre optic cable)
  - **Objective Lens & Focussing** – Good
  - **Remote Control Switches** – N/A
  - **Distal End** – Good condition
  - **Image Quality** – Satisfactory image (with signs of broken fibres)
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Leaking
  - **Overall Condition** – Satisfactory overall condition
  - **Dimension:** 4 x 500 mm

---

#### Lot 13 Pentax FI-13RBS Fiber Intubation Scope | SN A110040

- Condition Report:
- **Insertion Tube** – Poor condition (damaged close to handle)
  - **Bending mechanism & Angulation Control** – Good movements
  - **Light Guide Cable & Light Transmission** – Low light transmission (no fibre optic cable)
  - **Objective Lens & Focussing** – Good
  - **Remote Control Switches** – N/A
  - **Distal End** – Good condition
  - **Image Quality** – Satisfactory image (with several broken fibres)
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Small leak detected
  - **Overall Condition** – Satisfactory overall condition
  - **Dimension:** 4 x 500 mm

---

#### Lot 14 Fujinon EC530WL Video Colonoscope | SN 3C447A368



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

- Condition Report:
- **Insertion Tube** – Good condition
  - **Bending mechanism & Angulation Control** – Good movements & locks
  - **Light Guide Cable & Light Transmission** – Good
  - **Objective Lens & Focussing** – Good
  - **Remote Control Switches** – Fully functional
  - **Distal End** – Satisfactory condition (with cracks on the distal ring)
  - **Image Quality** – Very good image
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Pass
  - **Overall Condition** – Good overall condition (with scratch marks on handle)
  - **Dimension:** 13 x 1600 mm

---

**Lot 15 Fujinon EC530WL Video Colonoscope | SN 3C447A365**

- Condition Report:
- **Insertion Tube** – Good condition
  - **Bending mechanism & Angulation Control** – Good movements & locks
  - **Light Guide Cable & Light Transmission** – Good
  - **Objective Lens & Focussing** – Good
  - **Remote Control Switches** – Freeze button not working
  - **Distal End** – Satisfactory condition
  - **Image Quality** – Very good image
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Pass
  - **Overall Condition** – Good overall condition (with scratch marks on handle)
  - **Dimension:** 13 x 1600 mm

---

**Lot 16 Olympus CF-240AL Video Colonoscope | SN 2110225**

- Condition Report:
- **Insertion Tube** – Very good condition
  - **Bending mechanism & Angulation Control** – Good movements & locks
  - **Light Guide Cable & Light Transmission** – Good
  - **Objective Lens & Focussing** – Good
  - **Remote Control Switches** – Fully functional
  - **Distal End** – Good condition
  - **Image Quality** – Good image
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Pass
  - **Overall Condition** – Good overall condition (with signs of wear on handle)
  - **Dimension:** 12 x 1600 mm



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

#### Lot 17 Olympus GIF-XQ240 Video Gastroscope | SN 2032097

- Condition Report:
- **Insertion Tube** – Very good condition
  - **Bending mechanism & Angulation Control** – Good movements & locks
  - **Light Guide Cable & Light Transmission** – Good
  - **Objective Lens & Focussing** – Good
  - **Remote Control Switches** – Fully functional
  - **Distal End** – Good condition
  - **Image Quality** – Good image
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Pass
  - **Overall Condition** – Good overall condition (with signs of wear on handle)
  - **Dimension:** 10 x 1000 mm

#### Lot 18 Olympus GIF-XQ240 Video Gastroscope | SN 2032951

- Condition Report:
- **Insertion Tube** – Very good condition
  - **Bending mechanism & Angulation Control** – Good movements & locks
  - **Light Guide Cable & Light Transmission** – Good
  - **Objective Lens & Focussing** – Good
  - **Remote Control Switches** – Fully functional
  - **Distal End** – Good condition
  - **Image Quality** – Good image
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Pass
  - **Overall Condition** – Good overall condition (with signs of wear on handle)
  - **Dimension:** 10 x 1000 mm

---

#### Lot 19 Olympus GIF-XQ240 Video Gastroscope | SN 2235122

- Condition Report:
- **Insertion Tube** – Good condition (with a small dent)
  - **Bending mechanism & Angulation Control** – Good movements & locks
  - **Light Guide Cable & Light Transmission** – Good
  - **Objective Lens & Focussing** – Good
  - **Remote Control Switches** – Fully functional
  - **Distal End** – Good condition
  - **Image Quality** – Good image
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Pass
  - **Overall Condition** – Good overall condition
  - **Dimension:** 10 x 1000 mm



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

---

**Lot 20 Olympus PCF-2406 Video Colonoscope | SN 2930014**

- Condition Report:
- **Insertion Tube** – Very good condition
  - **Bending mechanism & Angulation Control** – Good movements & locks
  - **Light Guide Cable & Light Transmission** – Good
  - **Objective Lens & Focussing** – Good
  - **Remote Control Switches** – Fully functional
  - **Distal End** – Good condition
  - **Image Quality** – Good image
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Pass
  - **Overall Condition** – Good overall condition (with signs of wear on handle)
  - **Dimension:** 12 x 1600 mm

---

**Lot 21 Olympus CF-240AL Video Colonoscope | SN 2210407**

- Condition Report:
- **Insertion Tube** – Very good condition
  - **Bending mechanism & Angulation Control** – Good movements & locks
  - **Light Guide Cable & Light Transmission** – Good
  - **Objective Lens & Focussing** – Good
  - **Remote Control Switches** – Fully functional
  - **Distal End** – Good condition
  - **Image Quality** – Good image
  - **Instrument Channel (s)** – Clear
  - **Leak Test** – Pass
  - **Overall Condition** – Good overall condition (with signs of wear on handle)
  - **Dimension:** 12 x 1600 mm

---

**Lot 52 GE Logiq Book XP Portable Ultrasound (No Hard Drive) with 3C-RS Convex**

Serial No: 112669WX7

Manufactured: 02 2009

Accessories: Convex Probe S/N: 71600YP1 (3/2011)  
Mains adapter/ charger

Condition Report: Unit power up but the LCD is not working properly, display is distorted. The hard drive had been removed. Average physical condition.

---

**Lot 53 Sonosite M-Turbo Portable Ultrasound with C60X/5-2MHz Transducer and Power**

Manufactured: 04 2008

Condition Report: The ultrasound system powers up and completes the initialisation process successfully. Display screen, control panel and touchpad are functional. All available modes including 2D, Colour, Doppler and M mode are functional. The transducer is also working and the





UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

system produces clear images. The patient entry and review options are not accessible (when selected the unit continuously displays a message to wait for a few moments). Charger is included but the battery found to be not working at the time of test. Overall the unit is in good physical condition.

---

**Lot 193 Philips Heartstart MRX Defibrillator with ECG, NIBP and Test Loader Lead | DOM**

**Condition Report:** The defibrillator powers up and completes the initial self test successfully. Display screen, control panel and printer are in good working order. Both manual and AED modes are selectable and appear to be functional but have not been fully tested. Available parameters on the unit include ECG, SpO2 and NIBP. The lot comes with a battery which was found to be not working at the time of test. Mains power adaptor is not included. Overall the unit is in reasonable physical condition.

---

**Lot 194 Philips Heartstart MRX Defibrillator with SPO<sup>2</sup>, NIBP and Test Loader Lead | DOM**

**Condition Report:** The defibrillator powers up and completes the initial self test successfully. Display screen, control panel and printer are in good working order. Both manual and AED modes are selectable and appear to be functional but have not been fully tested. Available parameters on the unit include Pacer, ECG, SpO2 and NIBP. The lot comes with a mains power adaptor and a battery but the battery was found to be not working at the time of test. Overall the unit is in reasonable physical condition with minor signs of wear on some of the buttons.

---

**Lot 195 Storz Telecam SL Pal Camera Processor and Storz Telecam Camera Head | SN**

**Serial No:** EIP032089

**Manufactured:** 2005

**Accessories:** Telecam camera head

**Condition Report:** The Telecam SL PAL power up and the white balance is working. Good image quality was displayed when tested with camera head. System is in good overall condition.

---

**Lot 207 Draeger Oxylog 3000 Ventilator | DOM 20007 SN SRYB-0008**

**Accessories:** Mains adapter/charger

**Software:** Version 01.23

**Condition Report:** The Oxylog 3000 power up with mains and battery. System self-test completed ok. LCD, parameters control knobs and key pad are in good working order. Oxygen hose not included. System not tested fully with medical gas. Available vent modes: CMV, CPAP, PCV+ & SIMV. Lot is in good physical condition but not fully tested

---

**Lot 230 Conmed Linvatec HD 1080P Camera Processor | SN 70413 and Conmed Linvatec**



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

**Condition Report:** Both xenon light source and HD 1080P camera controller are powering up. The Xenon lamp and brightness control are working fine. Bulb life: 137. The camera controller was test with a compatible camera head and good image quality was displayed. System is in good physical and cosmetic condition.

---

**Lot 231 Conmed Linvatec Xenon 300W Light Source | SN 64803 and Conmed Linvatec**

**Condition Report:** Both xenon light source and HD 1080P camera controller are powering up. The Xenon lamp and brightness control are working fine. Bulb life: 359. The camera controller was test with a compatible camera head and good image quality was displayed. System is in good physical and cosmetic condition.

---

**Lot 282 Conmed IM4120 True HD 1080P Camera Head with Light Lead**

**Condition Report:** The HD 1080p camera head is in good working order when tested with a compatible controller. Good image quality was displayed. Zoom and focus is functional. Unit is in good overall condition.

---

**Lot 283 Conmed IM4120 True HD 1080P Camera Head with Light Lead**

**Condition Report:** The HD 1080p camera head is in good working order when tested with a compatible controller. Good image quality was displayed. Zoom and focus is functional. Unit is in good overall condition.

---

**Lot 284 Conmed IM4120 True HD 1080P Camera Head with Light Lead**

**Condition Report:** The HD 1080p camera head is in good working order when tested with a compatible controller. Good image quality was displayed. Zoom and focus is functional. Unit is in good overall condition.

---

**Lot 285 Conmed IM4120 True HD 1080P Camera Head with Light Lead**

**Condition Report:** The HD 1080p camera head is in good working order when tested with a compatible controller. Good image quality was displayed. Zoom and focus is functional. Unit is in good overall condition.

---

**Lot 286 Conmed IM4120 True HD 1080P Camera Head with Light Lead**

**Condition Report:** The HD 1080p camera head is in good working order when tested with a compatible controller. Good image quality was displayed. Zoom and focus is functional. Unit is in good overall condition.

---

**Lot 337 Conmed Linvatec True HD 1080P Camera Head | IM4120**

**Condition Report:** The HD 1080p camera head is in good working order when tested with a compatible controller. Good image quality was displayed. Zoom and focus is functional. Unit is in good overall condition.

---

**Lot 338 Storz Telecam Camera Head | SN RDG604112-H**



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

**Condition Report:** The Telecam 20212040 camera head is in good working order when tested with a compatible controller. Good image quality was displayed. Zoom and focus is functional. Unit is in good overall condition.

---

**Lot 339 Storz Telecam Camera Head | SN RKG609077-H**

**Condition Report:** The HD 1080p camera head is in good working order when tested with a compatible controller. Good image quality was displayed. Zoom and focus is functional. Unit is in good overall condition.

---

**Lot 340 Storz Telecam Camera Head | SN KG609312-H**

**Condition Report:** The HD 1080p camera head is in good working order when tested with a compatible controller. Good image quality was displayed. Zoom and focus is functional. Unit is in good overall condition.

---

**Lot 341 Storz Telecam Camera Head | SN KG619718-H**

**Condition Report:** The HD 1080p camera head is in good working order when tested with a compatible controller. Good image quality was displayed. Zoom and focus is functional. Unit is in good overall condition.

---

**Lot 342 Storz Telecam Camera Head | SN GG606628-H**

**Condition Report:** The HD 1080p camera head is in good working order when tested with a compatible controller. Good image quality was displayed. Zoom and focus is functional. Unit is in good overall condition.

---

**Lot 359 Haag Streit Slit Lamp with Tonometer and Eyepieces | SN 90010448**

**Condition Report:** The slit lamp powers up and the lamp and brightness control are in good working order. The binocular assembly is intact with clear optics and the system produces good images. Includes two sets of eyepieces (10x and 16x). The joystick control is functional but the covers for the roller wheels/rails are missing from both sides of the slit lamp. The chin rest adjustment and table height adjustment are in good working order. The fixation light appears to be not working. Tonometer is also included. Overall the unit is in satisfactory physical condition. The base plate of the storage box is missing. The table does not have wheels.

---

**Lot 360 Olympus Stack Trolley with OEV262, High Def LCD Monitor, Olympus Unit-TX**

**Serial No:** 7590349 (CV-290SL)

**Manufactured:** 09 2015

**Accessories:** Olympus Evis Lucera Elite Light source CLV-290SL, S/N: 7515696  
Olympus Evis Lucera Elite Processor CV-290SL, S/N: 7590349  
Olympus 26" LCD Monitor OEV262H S/N: 7533498  
Olympus Video cable MAJ-1911  
Olympus Keyboard



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

**Condition Report:** All equipment of the stack powers up. Processor and light source are working fine. CLV -290SL's xenon lamp are working. The keyboard and LCD monitor are fully functional. Video scope is not included, therefore the system image quality was not fully tested. System is in good physical and cosmetic condition.

---

**Lot 365 Datex Ohmeda Aisys Anaesthetic Machine with Vital Signs and Ventilator**

**Software:** 08.01

**Condition Report:** The anaesthetic machine powers up and completes the initial system self test successfully. Display screens and control panels are in good working order. Both the ventilator and the Carescape patient monitoring system appear to be functional but have not been fully tested. The breathing system is intact with bellows, flow sensors and O2 sensor in place (CO2 absorber canister is not included). The backup battery found to be working at the time of test. Air, O2, N2O, Suction and AGSS hoses are included. Overall the unit is in reasonable physical condition. Some of the buttons on the ventilator display console have been worn slightly.

---

**Lot 366 Erbe V10200D Electrosurgical Unit (No Foot Pedals) | DOM 03/2017 | SN 11427858**

**Software:** 2.3.5

**Condition Report:** The electrosurgical unit powers up and completes the initial system self test successfully. Display screen and control panel are in good working order. No further checks carried out. Overall the unit is in good physical condition.

---

**Lot 367 Datex Ohmeda Aisys Anaesthetic Machine with Vital Signs and Ventilator**

**Software:** 08.01

**Condition Report:** The anaesthetic machine powers up and completes the initial system self test successfully. Display screens and control panels are in good working order. Both the ventilator and the Carescape patient monitoring system appear to be functional but have not been fully tested. The breathing system is intact with bellows, flow sensors and O2 sensor in place (CO2 absorber canister is not included). The backup battery found to be working at the time of test. Air, O2, N2O, Suction and AGSS hoses are included. Overall the unit is in reasonable physical condition.

---

**Lot 368 Datex Ohmeda Aisys Anaesthetic Machine with Vital Signs and Ventilator**

**Software:** 08.01



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

**Condition Report:** The anaesthetic machine powers up and completes the initial system self test successfully. Display screens and control panels are in good working order. Both the ventilator and the Carescape patient monitoring system appear to be functional but have not been fully tested. The breathing system is missing the flow sensor module, flow sensors and O2 sensor (CO2 absorber canister is not included). The backup battery found to be working at the time of test. Air, O2, N2O, Suction and AGSS hoses are included. Overall the unit is in reasonable physical condition. Some of the buttons on the ventilator display console have been worn slightly.

---

**Lot 372 Datex Ohmeda Aestiva 5 Anaesthetic Machine | SN AMVL00162 | DOM 2012**

**Accessories:** Air, O2 & N2O hose  
AGSS Hose  
Central vacuum regulator and hose

**Software:** Version 1.4

**Condition Report:** The anaesthetic machine powers up and completes the initial system self test successfully. Pipeline pressure gauges, flowmeters and O2 flush. Anti-hypoxic feature and basal flow are also in good working order. Display screen and control panel of the 7100 ventilator are functional. All ventilation modes (volume control, pressure control and manual) are in good working order but a leak was observed in the breathing system. The flow sensor and O2 sensor are working fine Bellows and absorber all in place. The backup battery is working. Overall the unit is in good physical condition with minor signs of wear. Medical gas hoses are included.

---

**Lot 373 Datex Ohmeda Aestiva 5 Anaesthetic Machine | SN AMVL00164 | DOM 2007**

**Accessories:** Air, O2 & N2O hose  
AGSS Hose  
Central vacuum regulator and hose

**Software:** Version 1.4

**Condition Report:** The anaesthetic machine powers up and completes the initial system self test successfully. Pipeline pressure gauges, flowmeters and O2 flush. Anti-hypoxic feature and basal flow are also in good working order. Display screen and control panel of the 7100 ventilator are functional. All ventilation modes (volume control, pressure control and manual) are in good working order but a small leak was observed in the breathing system. The flow sensor and O2 sensor are working fine Bellows and absorber all in place. The backup battery is working. Overall the unit is in good physical condition with minor signs of wear. Medical gas hoses are included.

---

**Lot 374 Ethicon Mammotome Breast Biopsy System with Mammotome ST**

**Serial No:** 2300118

**Accessories:** Mammotome ST Holster



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

Mammotome EX Biopsy Device (ultrasound)

**Condition Report:** System powers up with the LCD working. System requires all devices to be connected.  
Unable to do any further tests

---

**Lot 375 Ethicon Mammotome Breast Biopsy System with Devicor Universal Targeting Set**

**Serial No:** 2304195

**Accessories:** Devicor Universal Targeting Set - Long 145mm  
Devicor MR Bladless Probe with Tube Set - Short 115mm  
System Operating Manual CD-ROM  
Mammotome Biopsy System Service Manual CD-ROM  
Control Module Interlock

**Condition Report:** System powers up with the LCD working. System requires all devices to be connected.  
Unable to do any further tests.

---

**Lot 376 Toshiba Nemio 10 Ultrasound with Toshiba PVM-375AT Convex Array Transducer**

**Serial No:** E2524090

**Manufactured:** 02 2001

**Associated Equipment:** Toshiba PVM-375AT Convex Array Transducer  
Serial Number: TDA12Z2875  
Manufactured: 12-2010

Mitsubishi P91 Printer

Sony SVO-9500MDP VCR

**Condition Report:** The ultrasound powers up and successfully completes its boot-up process. The CRT monitor, control panel function keys, trackball, TGC sliders and alphanumeric keyboard are in good working order. When tested using a phantom the probe produced satisfactory image quality, resolution, grey-scale and accurate caliper measurement were obtained. The functional system modes are 2D and M-Mode. The probe has major crystals dropout on the edge and a small section towards the middle of the image. The transducer membrane is discoloured, the cable sheath has a small cut and the strain relief is loose on the side of the transducer connector. The printer and the foot switch are in good working order. The VHS recorder powers up and appears to be working but was not fully tested. The door release button of the printer is broken but it can be opened. One of the plastic cover of the transducer holder is missing. Overall the ultrasound is in satisfactory physical condition with minor signs of wear.

---

**Lot 378 Esaote MyLab 25 Xvision Ultrasound (No HDD) with Esaote LA523 Transducer I**

**Condition Report:** The ultrasound unit powers up but does not display any information on the screen (the motherboard and the HDD have been removed). The probe was tested with a compatible unit and produced clear images with good resolution and greyscale. The transducer is in reasonable physical condition with minor scratches on the plastic case. The printer powers up but was not fully tested. Footswitch is included but was not fully tested. Overall the unit is in fair physical



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

condition.

---

**Lot 381 Olympus UHI-3 Insufflator | SN 1504286 | AN MP14700**

**Condition Report:** Unit power up with the numerical displays and key pad working fine. The flow and pressure settings are functional. Unit was not tested fully with CO2 gas cylinder. Unit is in fair physical condition with scuffs on the front panel.

---

**Lot 400 HillRom Airshields Resuscitaire | SN PN00093**

**Accessories:** Air & O2 hose

**Condition Report:** Unit power up with the radiant heater is working in all three mode, Preheat, Manual and skin temperature modes. The skin mode was not fully tested since the baby temperature probe is not included. The over head light is working as well. The oxygen auxiliary supply, O2 therapy, O2/Air blender and suction system are in good working order. The unit is in good physical condition.

**Lot 401 HillRom Airshields Resuscitaire | SN SW03290**

**Accessories:** O2 hose

**Condition Report:** Unit power up with the radiant heater is working in all three mode, Preheat, Manual and skin temperature modes. The skin mode was not fully tested since the baby temperature probe is not included. The over head light is working as well. The oxygen auxiliary supply, O2 therapy and suction system are in good working order. The unit is in good physical condition.

---

**Lot 448 Datex Ohmeda Aisys Anaesthetic Machine with Vital Signs and Ventilator**

**Software:** 08.01

**Condition Report:** The anaesthetic machine powers up and completes the initial system self test successfully. Display screens and control panels are in good working order. Both the ventilator and the Carescape patient monitoring system appear to be functional but have not been fully tested. The breathing system is intact with bellows, flow sensors and O2 sensor in place (CO2 absorber canister is not included). The backup battery found to be working at the time of test. Air, O2, N2O, Suction and AGSS hoses are included. Overall the unit is in reasonable physical condition.

---

**Lot 449 PFI Datex Ohmeda Anaesthetic Machine | DOM 2011 | AN 150671, F7 Module**

**Condition Report:** The anaesthetic machine powers up and completes the initial system self test successfully. Display screens and control panels are in good working order but the unit has not been fully tested. The Carescape control unit and the LCD monitor are not included. The breathing system is intact with bellows, flow sensors and O2 sensor in place (CO2 absorber canister is not included). The



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

backup battery found to be working at the time of test. Air, N2O, Suction and AGSS hoses are included but the O2 hose is missing. Overall the unit is in reasonable physical condition.

---

**Lot 475 Zeiss OPMI-1 Operating Microscope with Lens and Eyepieces | SN 82452 | AN**

**Serial No:** 82452

**Manufactured:** Est 1985

**Accessories:** Eye pieces 12,5x set  
Objective lens f=200

**Condition Report:** The Light source's lamp and intensity control are working. The optical system is in a fair condition with good magnification and focus. System is aged but functional.

---

**Lot 476 Storz Stack System with Storz Telecam SL Pal Processor | 2021202, Storz Pulsar**

**Serial No:** BF8644

**Manufactured:** Est. 2004

**Associated Equipment:** Storz AIDA Control Image capture unit  
Sony CRT Monitor PVM-20L2MD  
Storz Pulsar light source S/N: BF10081  
Storz Telecam SL PAL S/N: BF608999-P  
HP Desljet Printer 5650

**Accessories:** Foot switch  
Fibre optic Guide cable  
Camera Head Telecam S/N: CF612926-H  
Keyboard

**Software:** V1.2.2.4

**Condition Report:** All equipment power up on the stack trolley. The AIDA control touch screen is working with the user menu accessible. The patient registration and image capture are fully functional. Fair images are processed and displayed on the CRT monitor and touch screen. The Pulsar xenon lamp is not working but the halogen light out put and air pump are working fine. The HP printer needs new cartridge. System is in a fair overall condition.

---

**Lot 500 Sonosite iLook Portable Ultrasound with Transducer and Power Pack | DOM**

**Serial No:** 038L5D

**Manufactured:** 05 2007

**Accessories:** Linear array probe

**Software:** ARN Ver: 10.80.100.025

**Condition Report:** Unit power up with mains with LCD and soft keys working fine. System function menus are accessible and working. Image displayed are of fair quality. Gain adjustments are working. The internal battery is low, was not working during test. System is in a fair overall condition.

---

**Lot 503 Draeger Air Shields Resuscitaire | SN UV01019**





UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

**Condition Report:** The System powers up and display test is completed. The numerical displays, push buttons and soft keys are working fine. Pre-warm and manual mode are working and the radiant warmer heater can be adjusted. The Baby mode was not fully tested; skin temperature probe is not included. Overhead light is working fine. Pneumatic system was not tested. Mechanical cot tilt adjustment are working. The grill of the radiant warmer heater is missing. The corners of the mattress cover are damaged. The plastic cover for the suction unit is loose. The unit is in fair physical condition.

---

**Lot 513 Marco Slitlamp with Table and Built In Light Source | AN 34788**

**Condition Report:** The slit lamp powers up and the lamp and brightness control are in good working order. The binocular assembly is intact with eyepieces in place and the system produces clear images. The joystick control, chin rest adjustment and table height adjustment are in good working order. Overall the unit is in satisfactory physical condition. The light selector rotating control is slightly damaged. The rubber eyecaps are missing from the eyepieces. The table does not have wheels.

**Lot 522 Hitachi EUB 5500 Ultrasound with Convex and Transvaginal Transducers | SN**

**Condition Report:** .

---

**Lot 523 Toshiba Aplio XG Ultrasound (No Transducers) | DOM 01/2010 | SN 99G1015432**

**Condition Report:** The ultrasound system powers up and completes the initialisation process successfully. Display screen, touch screen console, control panel and trackball are in good working order. The lot does not include any transducers but the unit was tested with a compatible transducer and the system produced clear images. The functional system modes include 2D, ADF, CDI, POWER, PW and M-mode. The printer is also functional. Overall the ultrasound unit is in satisfactory physical condition with general signs of wear. Some of the front panel buttons are without the plastic cover and labels. The storage drawer is slightly loose.

---

**Lot 524 Philips IU22 Ultrasound with Linear Transducer (No HDD) | DOM 03/2008 | SN**

**Condition Report:** The ultrasound system powers up but displays 'no video input' on the LCD monitor. The hard drives have been removed. The transducer is physically intact but has not been tested. The printer is functional. Overall the ultrasound unit is in reasonable physical condition.

---

**Lot 525 Toshiba Xario Ultrasound (No Transducers) | DOM 2009 | SN 15A0925055**

**Condition Report:** The ultrasound system powers up and completes the initialisation process successfully. Display screen, control panel and touch screen menu are in good



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

working order. The functional system modes include 2D, CDI, POWER, PW and M . Tested with a compatible transducer and with phantom the system produced clear images with good resolution and greyscale. The caliper measurements are also within the limits. The printer is working, and overall the ultrasound unit is in reasonable physical condition. The outer casing of the main unit has some major cracks on the sides. Some of the rotary knobs have minor cracks and one of the plastic cover of the button is missing.

---

**Lot 527 Toshiba Xario XG Ultrasound and Sony Printer (No Transducers) | DOM 11/2007 |**

**Condition Report:** The ultrasound system powers up and completes the initialisation process successfully. Display screen, touch screen console, control panel and trackball are in good working order. The lot does not include any transducers but the unit was tested with a compatible transducer and the system produced clear images. The functional system modes include 2D, Dynamic Flow, CDI, POWER, PW and M-mode. The printer is also functional. Overall the ultrasound unit is in reasonable physical condition with minor signs of wear. Two of the front panel buttons are without the plastic cover and labels.

---

**Lot 530 Echosens Fibroscan 502 Scanner | SN F00696 | AN 507833**

**Serial No:** F00696

**Condition Report:** Hard drive had been formatted and wiped

---

**Lot 531 Haag Streit Bern Slit Lamp with Eyepieces On Table | SN B90027141 | AN 30-24**

**Condition Report:** The on/off control knob for power supply of the slit lamp is missing and the power cable has been cut. The optics appear to be clear but the unit cannot be fully tested. The joystick control, chin rest adjustment and table height adjustment are in good working order. The binocular assembly is intact and the eyepieces are also included. Overall the unit is in satisfactory physical condition.

---

**Lot 532 Karl Storz Stack Trolley, Storz Endoflator | SN EF9733-B, Xenon Nova 300 Light**

**Serial No:** 0250-4903-0464

**Manufactured:** Est. 2003

**Software:** 2.2.00 (MediLive Image Box)

**Condition Report:** All equipment power up on the stack trolley. The Zeiss MediLive Image Box power up and the function menus are working. The camera controller power up and colour is display. camera head is not included, therefore image processing was not tested. The light source's xenon lamp is working fine and so is the brightness control. The Sony CRT monitor is working. System is in a reasonable physical condition.



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

---

**Lot 533 Storz Stack Trolley with Storz Tele Pack Pal and Sony Colour Video Printer | SN**

**Serial No:** SZ4599-C

**Manufactured:** Est. 2010

**Condition Report:** The system power with the LCD and keyboard working fine. The light source halogen lamp is working. The system was tested with a compatible camera head and good live images were displayed on the LCD. The image storage was not tested, and memory card is not included. Lot is in good overall condition.

---

**Lot 534 Storz Stack Trolley with Storz Tele Pack Pal and Sony Colour Video Printer |**

**Serial No:** KB3597-B

**Manufactured:** Est. 2010

**Associated Equipment:** Sony DVD Recorder

**Condition Report:** The system power with the LCD and keyboard working fine. The light source halogen lamp is working. The system was tested with a compatible camera head and good live images were displayed on the LCD. The image storage was not tested, and memory card is not included. Lot is in good overall condition.

---

**Lot 539 Valleylab Force Force EZ Diathermy with Foot Switches | SN F0L47308**

**Serial No:** EZ-8F0L4730B

**Manufactured:** 06 2000

**Associated Equipment:** Force EZ User Manual  
Set of Monopolar Footswitches  
Bipolar Footswitches (x2)

**Accessories:** Trolley

**Condition Report:** Unit power up with the alphanumerical displays and function keys working fine. The display power up test completed. Patient return plate monitoring circuit is functional. The system was tested with a ESU analyser in both bipolar and monopolar functions and different modes. All the RF outputs were within the set limits. Includes monopolar and bipolar footswitches. Key membrane for monopolar/bipolar selector is worn, but still functional. Unit, accessories and associated equipment are all in good physical condition.

---

**Lot 540 Valleylab Force EZ C Diathermy with Foot Pedals | SN F6H9285B**

**Serial No:** F6H9285B

**Manufactured:** 08 2006

**Associated Equipment:** EZ C Diathermy Schematics Supplement  
Set of Monopolar Footswitches  
Bipolar Footswitch  
REM Polyhesive Adult Patient Return Electrodes

**Accessories:** Trolley with 4-way extension cable

**Condition Report:** Unit power up with the alphanumerical displays and function keys working fine. The display power up test completed. Patient return plate monitoring circuit is functional. The system was tested with a ESU analyser in both bipolar and monopolar functions and different modes. All the RF outputs were within the set limits. Includes monopolar



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

and bipolar footswitches. Unit, accessories and associated equipment are all in fair physical condition, with slight rusting on top shelf and loose handle.

---

**Lot 541 Olympus WM-SC Work Station with Sony Triniton Monitor, Sony LCD Monitor,**

**Serial No:** CV-S40

**Manufactured:** 2003

**Accessories:** Insufflators UHI-3  
Light source CLV-S40  
Digital Processor CV-S40  
Sony Colour video player UP-21MD  
Sony Digital Capture Unit UPA-P100MD  
Camera Leads OTV-S7  
Camera Leads OTV-SP1H-N-12E  
Sony CRT Monitor PVM-20M2MDE  
Sony LCD Monitor LMD-1420MD

**Condition Report:** All components power-up. Displays in satisfactory working order for both PVM-20M2MDE and LMD-1420MD respectively. CD drive on UP-21MD opens/closes as expected. UPA-P100MD currently untested. UHI-3 not tested with CO<sub>2</sub>, but appears to work satisfactorily. CV-S40 and CLV-S40 are also in satisfactory working condition. OTV-SP1H-N-12E appears to work in correct manner, with enhance function and camera working as expected (i.e. image resolution adjusting/no flickering on screen), but OTV-S7 was not recognised by the user interface. Good physical condition.

---

**Lot 544 Stack Trolley with Fujinon LCD Monitor | DOM 12/2007 | SN 3V432A276, System**

**Condition Report:** All units and the stack trolley power up ok. The video processor, light source and LCD monitor are in good working order. Tested with a compatible video endoscope, the system produced clear images and the white balance setting, colour adjustment and light intensity adjustment are all functional. Overall the endoscopy stack system is in good physical condition. The xenon lamp counter is approx. 50%.

---

**Lot 556 Aloka Prosound SSD-4000 Ultrasound with 3 x Transducers | DOM 2002 | SN**

**Condition Report:** The ultrasound system powers up and completes the initial self test successfully. The monitor, control panel and trackball are all functional. When tested with a phantom two of the transducers and the system produced clear images with satisfactory resolution and greyscale and accurate caliper measurements. All system modes including B, M, D and FLOW are functional. The convex probe produces satisfactory images and is in reasonable physical condition with some signs of wear. The endocavitary probe produces satisfactory images and is in reasonable physical condition with a small section of crystals drop out and a damage at the end of the cable close to the unit. The UST-934N probe has not been tested because not compatible and is in



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

reasonable physical condition with a major crack on the plastic case and the rubber membrane slightly damaged. The printer is also in good working order. Overall the unit is in reasonable physical condition with some signs of wear.

---

**Lot 563 Olympus OB300 Colposcope with Eyepieces and Camera | SN 203513**

**Condition Report:** The colposcope powers up, lamp and brightness control are in good working order and the fibre optic cable is in place. The binocular assembly and the eyepieces are intact, the zoom and focus controls are also operational and the system produces clear images. The video camera does not have a power supply and therefore could not be tested. Overall the unit is in reasonable physical condition.

---

**Lot 564 Storz Stack Trolley with Monitor and Wide View Monitor, SCB Electronic**

**Manufactured:** Est. 2009

**Associated Equipment:** Storz Light source Xenon 300  
Storz Image 1 Hub  
Aida Control  
Electronic Endoflator  
HP Destjet Printer 6940

**Accessories:** Key board & mouse  
Image 1 camera head

**Condition Report:** All equipment power up on the stack trolley. The AIDA power up but failed to boot up, the hard drive had been removed. Touch screen is working. The camera controller failed to display any images when the camera is connected. Once the camera is disconnected colour bars is displayed on the LCD monitor. The light source's xenon lamp is working fine and so is the brightness control. The HP printer was not fully tested. System is in a reasonable physical condition with the above mentioned issues.

---

**Lot 568 Valleylab Force FXC Diathermy and Optimumm Smoke Evacuator (No Foot**

**Serial No:** 8CF5D 37335A

**Manufactured:** 03 2005

**Associated Equipment:** Valleylab OptiMumm Smoke Evacuator  
Smoke Evacuator Service Manual

**Accessories:** Trolley

**Condition Report:** Unit power up with the alphanumerical displays and function keys working fine. The display power up test completed. Patient return plate monitoring circuit is functional. The system was tested with a ESU analyser in both bipolar and monopolar functions and different modes. All the RF outputs were within the set limits. Foot switches are not included. The unit is in fair physical condition with few rusty patches on the handle and bottom self. Smoke evacuator powers-up, but the vacuum pump failed to run. Filter is not included.



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

**Lot 569 Valleylab Force FXC Diathermy and Optimumm Smoke Evacuator (No Foot**

**Serial No:** 8CF5F39094A

**Manufactured:** 06 2005

**Associated Equipment:** Valleylab OptiMumm Smoke Evacuator  
Smoke Evacuator User Manual  
Force FXC Diathermy User Manual

**Accessories:** Trolley

**Condition Report:** Unit power up with the alphanumerical displays and function keys working fine. The display power up test completed. Patient return plate monitoring circuit is functional. The system was tested with a ESU analyser in both bipolar and monopolar functions and different modes. All the RF outputs were within the set limits. Foot switches and power cable are not included. The unit is in fair physical condition with few rusty patches on the handle. Smoke evacuator powers-up, but unit causes mains to trip. Filter is not included.

---

**Lot 570 Valleylab Force FXC Diathermy and Optimumm Smoke Evacuator (No Foot**

**Serial No:** 8CF5D37722A

**Manufactured:** 04 2005

**Associated Equipment:** Valleylab OptiMumm Smoke Evacuator  
Smoke Evacuator Service Manual  
Force FXC Diathermy User Manual  
Split-plate cool contact

**Accessories:** Trolley

**Condition Report:** Unit power up with the alphanumerical displays and function keys working fine. The display power up test completed. Patient return plate monitoring circuit is functional. The system was tested with a ESU analyser in both bipolar and monopolar functions and different modes. All the RF outputs were within the set limits. Foot switches are not included. The unit is in fair physical condition with few rusty patches on the handle. Smoke evacuator powers-up and vacuum pump runs as expected. Filter is not included.

**Lot 571 Valleylab Force FXC Diathermy and Optimumm Smoke Evacuator (No Foot**

**Serial No:** 8CF0J15172A

**Manufactured:** 10 2006

**Associated Equipment:** Valleylab OptiMumm Smoke Evacuator  
Force FXC Diathermy User Manual  
Split-plate cool contacts

**Accessories:** Trolley

**Condition Report:** Unit power up with the alphanumerical displays and function keys working fine. The display power up test completed. Patient return plate monitoring circuit is functional. The system was tested with a ESU analyser in both bipolar and monopolar functions and different modes. All the RF outputs were within the set limits. Foot switches are not included. The unit is in fair physical condition with few rusty patches on the handle, top shelf and bottom self. Smoke evacuator powers-up and vacuum pump runs as



UK Head Office: Gloucester Road Trading Estate Malmesbury Wiltshire SN16 9JT  
+44 (0) 1666 822577 sales@hilditchgroup.com www.hilditchgroup.com

expected. Filter is not included.

---

**Lot 572 Valleylab Force FXC Diathermy and Optimumm Smoke Evacuator (No Foot**

**Serial No:** 8CF5F39217A

**Manufactured:** 06 2005

**Associated Equipment:** Valleylab OptiMumm Smoke Evacuator  
Smoke Evacuator User Manual (x2)  
Smoke Evacuator Service Manual  
Force FXC Diathermy User Manual

**Accessories:** Trolley

**Condition Report:** Unit power up with the alphanumerical displays and function keys working fine. The display power up test completed. Patient return plate monitoring circuit is functional. The system was tested with a ESU analyser in both bipolar and monopolar functions and different modes. All the RF outputs were within the set limits (except the cut mode which was slightly outside the acceptable limits). Foot switches are not included. The unit is in fair physical condition with few rusty patches on the handle and bottom self. Smoke evacuator powers-up and vacuum pump runs as expected. Filter is not included.

---